

## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

Post Office Block (Boise Basin Museum)  
Northwest corner of Wall and Montgomery Streets  
Idaho City  
Boise County  
Idaho

HABS No. ID-15

Documentation: 5 exterior photos (1976)  
2 interior photos (1976)  
1 photocopy of ca. 1953 photo  
7 data pages (1974)  
1 set of field records (1974, including 1 field notebook,  
1 field photo)

- ID-15-1 Duane Garrett, Photographer 1976  
EAST (FRONT) ELEVATION
- ID-15-2 Duane Garrett, Photographer 1976  
NORTHWEST CORNER
- ID-15-3 Duane Garrett, Photographer 1976  
WEST (REAR) ELEVATION
- ID-15-4 Duane Garrett, Photographer 1976  
BRICK WORK DETAIL, WEST ELEVATION
- ID-15-5 Duane Garrett, Photographer 1976  
BRICK WORK AND BRACING DETAIL, NORTHWEST CORNER
- ID-15-6 Duane Garrett, Photographer 1976  
VIEW OF MUSEUM, LOOKING WEST FROM MAIN ENTRANCE
- ID-15-7 Duane Garrett, Photographer 1976  
INTERIOR OF MAIN DOORWAY ON EAST WALL
- ID-15-8 Photocopy of old photo shows a view of old  
post office before the 1958 restoration, taken  
circa 1953. Original photograph at Idaho Historical Society  
Boise, Idaho.